

Office-chair repair kit

The repair kit consists of two metal bars, which are symmetric to each other. In addition, four screws M6x25 are needed.

Markus Kuhn, Computer Laboratory 2005-12-01

http://www.cl.cam.ac.uk/~mgk25/chairs/